




ФИГРОМЕТР ПСИХРОМЕТРИЧЕСКИЙ
ВИТ - 2

РАЗНОСТЬ ПОКАЗАНИЙ ТЕРМОМЕТРОВ, °C
1,0 1,5 2,0 2,5 3,0 3,5 4,0 4,5 5,0 5,5 6,0

ОТНОСИТЕЛЬНАЯ ВЛАЖНОСТЬ, %	90	85	81	76	71	67	63	58	54
20	90	85	81	76	71	67	63	58	54
21	90	85	82	77	73	69	64	59	55
22	91	85	82	77	73	69	64	59	56
23	91	86	82	78	74	70	66	62	59
24	91	87	83	79	75	71	67	63	60
25	92	88	84	80	76	72	68	65	61
26	92	88	84	80	77	73	69	66	62
27	92	88	84	81	77	73	70	66	63
28	92	88	85	81	78	74	71	67	64
29	92	89	85	82	78	75	71	68	65
30	92	89	85	82	78	75	72	69	66
31	93	89	86	82	79	76	72	69	66
32	93	89	86	83	79	76	73	70	67
33	93	89	86	83	79	76	73	70	67
34	94	90	86	83	80	76	73	70	67
35	94	90	86	83	80	77	74	71	68
36	94	90	87	83	80	77	74	71	68
37	95	90	87	84	81	78	75	72	69
38	95	90	87	84	81	78	75	72	70
39	95	91	87	84	81	78	75	72	70
40	96	91	88	85	82	79	76	73	70

РАЗНОСТЬ ПОКАЗАНИЙ ТЕРМОМЕТРОВ, °C
6,5 7,0 7,5 8,0 8,5 9,0 9,5 10,0 10,5 11,0 11,5

ОТНОСИТЕЛЬНАЯ ВЛАЖНОСТЬ, %	40	35	30	25	20	15	10	5
20	40	35	30	25	20	15	10	5
21	41	36	31	26	21	16	11	6
22	42	37	32	27	22	17	12	7
23	43	38	33	28	23	18	13	8
24	44	39	34	29	24	19	14	9
25	45	40	35	30	25	20	15	10
26	46	41	36	31	26	21	16	11
27	47	42	37	32	27	22	17	12
28	48	43	38	33	28	23	18	13
29	49	44	39	34	29	24	19	14
30	50	45	40	35	30	25	20	15
31	51	46	41	36	31	26	21	16
32	52	47	42	37	32	27	22	17
33	53	48	43	38	33	28	23	18
34	54	49	44	39	34	29	24	19
35	55	50	45	40	35	30	25	20
36	56	51	46	41	36	31	26	21
37	57	52	47	42	37	32	27	22
38	58	53	48	43	38	33	28	23
39	59	54	49	44	39	34	29	24
40	60	55	50	45	40	35	30	25

СКОРОСТЬ АСПИРАЦИИ 01,0-3 до 1,0 м/с